

Ultrasonic Cleaners liquids

How to use

Nom ▲	ph	Dilution dans l'eau %	Température du bain de lavage
AC	2.50	10-10	50
AF	0.00	5-10	40
CL4%	7.00	2-4	30
DW1		0-0	
ML	10.00	5-10	65
PCB	11.00	0-0	40
RC	13.00	0-0	60
RG	8.00	0-0	40
SF	13.00	8-10	60
UG	7.00	5-10	40
Winch Clean 1	7.00	1-10	60
Winch Clean 2	14.00	5-10	70

Compatibility

Nom ▲	Aluminium	Acier	Laiton	Cuivre
AC	1	4	4	4
AF	0	2	1	1
CL4%	4	5	5	5
DW1	5	5	5	5
ML	5	5	5	5
PCB	2	5	3	4
RC	0	5	2	2
RG	5	5	5	5
SF	0	5	2	2
UG	5	5	5	5
Winch Clean 1	5	5	5	5
Winch Clean 2	0	5	2	2

Residuals removal

Nom ▲	Huile	Graisse	Oxydes	Calcaire	Plâtres	Alginate	Ciments	Eau	Déchets organiques
AC	1	1	3	3	0	0	0	0	3
AF	2	2	5	5	0	0	0	0	3

Nom ▲	Huile	Graisse	Oxydes	Calcaire	Plâtres	Alginates	Ciments	Eau	Déchets organiques
CL4%	2	1	0	0	0	0	0	0	5
DW1	0	0	0	0	0	0	0	5	0
ML	5	4	2	0	0	0	0	0	4
PCB	2	2	2	0	0	0	0	0	4
RC	3	2	0	0	0	0	5	0	4
RG	0	0	0	0	5	4	0	0	2
SF	3	2	1	0	0	0	5	0	4
UG	4	1	1	0	0	0	0	0	4
Winch Clean 1	3	2	0	0	0	0	0	0	4
Winch Clean 2	5	5	1	0	0	0	0	0	4

Properties

Nom ▲	Dewatering et protection	Désincrustant	Détergent	Désinfectant
AC	0	4	3	0
AF	0	5	2	0
CL4%	0	0	4	5
DW1	5	0	0	0
ML	0	0	5	0
PCB	0	0	4	0
RC	0	5	0	0
RG	0	5	1	0
SF	0	0	4	0
UG	0	0	4	0
Winch Clean 1	0	0	5	0
Winch Clean 2	0	0	3	0